

IN	ICIDENT REPORTING FORM
[X] Initial report	
[] Updated	School: BT Washington HSPVA
	Principal: Tracie Fraley
	Time: 8 AM (8/16), 7:30 AM (8/17), 11:45 AM (8/18) Date: 8/16, 8/17, 8/18
Principal Requests	Individual Completing Form: Tracie Fraley
Letter to Parents	Phone #: 972-925-1200
	Other Contact: www.dallasisd.org/btw
	FACT SHEET
here at BTW. Due to the dangerously hi alternative locations on the 16th and 17t school this morning (the 18th). The air been here all week and late at night tryin part(s) and steps necessary to repair the	the air conditioning has not been working Monday the 16th and Tuesday the 17th igh temperatures and our inability to coll the building, we have relocated the staff to the the problems were solved and as a result - so we have been at has now quit working (as of 11 AM today, 8/18) - DISD maintenance and TAC have ng to fix the problems. They have located the problem and are looking for the problems completely. Thus far - they believe it is a part that needs to be replaced to discussing who will pay for the part, perform the repairs, troubleshoot fixing the
I am moving faculty for our afternoon pr	peratures expected this afternoon and our inability to ventilate and cool the building rofessional development session and meetings off site again for the remainder of the It Belt Line Road and the Toll Road (thanks to K. Allen!) in Dallas for lunch and our 8/18).
intermittently working in some places bu the problems resolved PRIOR to school o	ol looks deserted - it is! We are hoping for air tomorrow Right now - it is ut in most places it is not. We ask parents and others for patience as we try and get opening. Our facilities supervisor and a skeleton staff will be here for maintenance our remote sites - parents can email the appropriate staff with EMERGENCY rmal operations.
List Name(s) of Individuals Involved	l: All BTW faculty and staff
XEmployee(s)	
NoneStudent(s) (if stud	dent, identify): Grade Age
D.O.B	
Time Event Occurred: Initial 8/14 at on 8/18	approximately 1 PM; subsequently 7 AM on 8/16, 7 AM on 8/17 and 11 AM
Location/School/Other: Entire scho	ool - Booker T. Washington HSPVA; 2501 Flora Street; Dallas, TX 75201
Others Involved: DISD Maintenance	e; TAC



Describe action being taken by school and emergency personnel: Moving faculty and staff to alternate locations as follows:

8/16: One Arts Plaza – 15th floor meeting space 8/17: 1st United Methodist Church, Dallas ISD 8/18: North Dallas – Belt Line Road, Dallas, TX

Status of individuals involved: All BTW faculty and staffsafely shuttled and moved to new location! Emergency BTW staff remaining on site for HVAC and district staff to make repairs and trouble shoot HVAC systems.

Witnesses: All of BTW faculty and staff!

People Notified: WLSC staff, PTSA president, AB president, DISD public relations staff, SBDM Chair

email to: ghodges@dallasisd.org
email to: jdahland@dallasisd.org
email to: cvelasco@dallasisd.org